Approved For Release 2002/06/2 CIA App78B04747A001500030013-9

NPIC/TDS/D-1091-67 24 October 1967

	MEMORANDUM FOR THE RECORD	
25X1A	SUBJECT: Chip Comparator Progress Report	
€ 25X1A	1. During the period 2-4 August personnel installed a temporary field modification to the 405 AM chip comparator to keep it in an operational status until such time as it can be sent to the factory for permanent modifications. On the 17th, 18th, and 23rd of August the technician returned to make minor adjustments to the machine. Since the 23rd of August, no maintenance adjustments of any sort have been made to the instrument except for water replenishment.	25X1A
	2. TDS will observe the operational reliability of the comparators without making any maintenance adjustments until the reliability drops below acceptable limits in order to determine mean time between failure. As soon as sufficient data is available, a routine preventative maintenance schedule will be set up to keep all of the comparators in peak operating condition.	.
25X1A	3. At present, two 405B comparators are at	25X1A
25X1A	4. Based on the performance record of the 405AM for the past two months, indications are that the fundamental operational reliability problems with the chip comparators have been resolved, but that additional funding will be required. A cost analysis and work statement has been received from and is being forwarded to the respective components under separate memo for action.	

DECLASS REVIEW by NIMA/DOD

Approved For Release 2002 46 7 - CIA-RAP78B04747A001500030013-9

- 5. An additional consideration concerning the operational use of the chip comparators, not previously covered, is the availability of computer time and software. Since four out of the six chip comparators are exclusively on-line, the operational availability of the chip comparators must therefore take into consideration the data processing as an essential element of consideration. It is my understanding from talking to IAS, TDS, and DIA personnel that that the data processing problem is of extreme concern to them. Also affecting the operational acceptability of the chip comparators are the building facility requirements and training programs. Since the chip comparators are highly sophisticated pieces of equipment, they impose special building facility and training requirements on the Center.
- In summary, TDS feels that the solution for the basic reliability and maintainability of the chip comparators has been resolved from the technical viewpoint, but that the operational acceptability is dependent upon additional considerations beyond its control; namely, the required additional funding, the data processing capability, training, and building facility maintenance.

 25X1A
•

Distribution:

Original - Route & File

1 - O/Dir (Technical Advisor)

1 - O/Dir (Special Assistant)

1 - NPIC/PAG

1 - NPIC/IAS

1 - NPIC/TID

25X1A

1 - DIA (Attn: 1 - NPIC/TDS/EPS

1 - NPIC/TDS/DS

1 - NPIC/TDS

DATE OF DOC DATE REC'D DATE OUT. SUSPENSE DATE	CONTROL NO.					
FROM See Distriction	ROUTING	DATE SENT				
the correspondencions Cher Computations.						
COURIER NO. ANSWERED MARGELY	1/4/- - 9°	· 4				

STATINTL

STATINTL